

FIRESTONE

FIRESTONE TIRE & RUBBER CO.

Akron 17, Ohio

Firestone outboard motors are manufactured for Firestone Tire & Rubber Co. by Hartford Division, West Bend Company, Hartford, Wisconsin, or by McCulloch Corporation, Los Angeles 45, California.

Service procedures on these units will not differ greatly from those given for similar motors bearing manufacturer's brand name. This does not necessarily mean, however, that parts are interchangeable. When parts are required for these motors, refer to PARTS PROCUREMENT INFORMATION following the model listing.

Firestone Model	Year	Manufacturer	Section
10-A-71	1955	Scott	3.6 HP
10-A-102	1955	Scott	5 HP
10-A-103	1955	Scott	7.5 HP
10-A-104	1955	Scott	10 HP
10-A-105	1955	Scott	16 HP
10-A-111	1956-59	Scott	3.6 HP
10-A-112	1956-59	Scott	5 HP
10-A-113	1956-57	Scott	10 HP
10-A-114	1956-59	Scott	16 HP
10-A-115	1956	Scott	30 HP
10-A-116	1956	Scott	30 HP
10-A-117	1957	Scott	40 HP
10-A-118	1957	Scott	40 HP
10-A-120	1958-59	Scott	10 HP
10-A-121	1958-59	Scott	40 HP
10-A-122	1958-59	Scott	40 HP
10-A-123L	1958-59	Scott	40 HP
10-A-130	1960-62	West Bend	2 HP
10-A-131	1960-62	West Bend	7½ HP
10-A-132	1960	West Bend	8 HP
10-A-133	1960-62	West Bend	12 HP
10-A-135	1960-62	West Bend	40 HP
10-A-134	1961-62	West Bend	25 HP

PARTS PROCUREMENT

Parts for Firestone Outboard Motors may be ordered through any Firestone Home & Auto Supply Store. A complete stock is maintained at the following two supply points:

Firestone Home & Auto Supply Whse.
Box 192
Berea, Ohio

Firestone Home & Auto Supply Whse.
Box 10041, McKellar Station
Memphis, Tennessee